

## Construction Defect Documentation

### Field Inspection

Stability Assessment  
January 28, 2010

### Walter P Moore

Stability Assessment  
January 28, 2010

### Field Inspection

Stability Assessment  
July 14, 2011

### Perini Building Company

Stability Report  
July 14, 2011


### Repair Sketch

### LVI Environmental Services

Abatement Plan  
August 11, 2011




January 28, 2010






January 28, 2010







January 28, 2010






February 12, 2010





February 12, 2010






February 12, 2010





February 12, 2010









February 12, 2010






February 12, 2010






February 12, 2010







February 12, 2010








February 12, 2010






February 12, 2010





Typical Link Beam Repair Sketch, Plan



ADDITIONAL ROW

Typical Link Beam Repair Sketch, Section

